

# U.S ENVIRONMENTAL PROTECTION AGENCY SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION INDOOR AIR QUALITY QUESTIONNAIRE AND BUILDING INVENTORY

Preparer's Name: Robert Whittier/Carl Overpeck Date Prepared: 22-February-2014

Preparer's Affiliation: EPA/START Phone No. 907-257-5000 ext 3303



#### 1. OCCUPANTS:

#### Unit #1

Last Name: _(b) (6)	First Name: (b) (6)			
Property address: _EA Block 26A Lot 2; 736 East 3 <sup>rd</sup> Avenue Unit #1; Anchorage, AK. 99515				
Home Phone:	Office/Cell Phone:			
Number of Occupants/persons at this location:	_(b) (6) _ Age of Occupants:(b) (6)			
Unit #2				
Last Name: _(b) (6)	First Name: (b) (6)			
Property address: EA Block 26A Lot 2; 736 East 3 <sup>rd</sup> Avenue Unit #2; Anchorage, AK. 99515				
Home Phone: (b) (6)	Office/Cell Phone:			
Number of Occupants/persons at this location:	(b) (6)_ Age of Occupants:(b) (6)			


2a. LANDLORD/MAINTENANCE MA	AN	
Last Name: _(b) (6)	First Name: _	(b) (6)
Property address: <u>EA Block 26A Lot 2</u>	2; 730 East 3 <sup>rd</sup> Avenue U	nit #3, Anchorage, AK. 99515
Home Phone:	Office/Cell Phone: _	(b) (6)
2b. OWNER		
_ast Name:(b) (6)	First Name	e:(b) (6)
Mailing/Home address:(b) (6)	; Anchorage, AK. 99	515
Home Phone: (b) (6)	Office/Cell P	hone:(b) (6)
If residential, type of proper	ty:	
[] Ranch	[ ] 2-Family	[ ] 3-Family
[ ] Raised Ranch	[ ] Split Level	[ ] Colonial
[ ] Cape Cod	[ ] Contemporary	[ ] Mobile Home
[X] Duplex	[ ] Apartment House	[ ] Townhouses/Condos
[ ] Modular	[ ] Log Home	Other:
If multiple units, how	v many? <u>2</u>	
If commercial, type?	<u>N/A</u>	
Business type(s): _	N/A	
Does the business in	nclude residences? [ ]	Y [X] N
Other Building Characteristics:		
Number of floors:	2	Approximate building age: <u>~50</u>
Is the building insulate	ed? [X] Y [ ] N	How air tight? [ ] Tight [X] Average

4. DASEWIENT AND CONSTRUCTION	N CHARACTERISTICS (	Circle all triat apply)	
<ul> <li>a. Above grade construction:</li> </ul>	[X] wood [ ] concre	ete[]stone[]brick[]other_	
b. Basement type:	[ ] full [X] crawls	space [X] slab [ ] other	
c. Basement floor:	[X] concrete [ ] c	lirt [ ] stone [ ] other	
d. Basement floor:	[X] uncovered [ ]	covered, covered with	
e. Concrete floor:	[X] unsealed [ ]	sealed, sealed withsome p	oaint
f. Foundation walls:	[ ] poured [X] blo	ock [ ] stone [ ] other	
g. Foundation walls:	[X] unsealed [ ]	sealed, sealed with <u>liner</u>	
h. The basement is:	[] wet [] damp	[X] dry [ ] moldy	
i. The basement is:	[ ] finished [ ] ur	nfinished [X] partially finishe	d
j. Sump present?	[ ] Y [X] N		
k. Water in sump?	[ ] Y [ ] N[X] N	IA	
I. Sump covered/sealed?	[]Y []N[X]N	IA	
m. Floor drains present?	[]Y []N[X]N	IA	
n. Perimeter trench drains present	? []Y[]N[]	IA UNKNOWN	
o. Indoor cisterns/drywell?	[]Y[X]N[]N	IA	
p. Laundry chute to 1 <sup>st</sup> or 2 <sup>nd</sup> Floors	? [] N [X] Y [] ?	NA	
Basement/lowest level depti	n below grade: <u>~5</u>	(feet)	
Diner covered gravel crawl spaces, sla  Other Comments:  5. HEATING, VENTING and AIR COllidentify all that apply and his	b cracks, utility penetration  NDITIONING  ghlight primary:	ons	
[X] Hot air circulation [	] Heat pump	[ ] Hot water baseboard	
	] Stream radiation		
[ ] Electric baseboard [ ] Other:		[ ] Outdoor wood boiler	
Approximate age of heating	system(s): 1-2 years		
The primary type of fuel use	d is:		
[ ] Electric [	Fuel Oil Propane Coal	[ ] Kerosene [ ] Solar	
Domestic hot water tank fue	led by:Natural Ga	s	
Fuel oil storage location/cor	ndition/size, if applicable	e: <u>N/A</u>	
Boiler/furnace located in:	[X] Basement	[ ] Outdoors [ ] Main	Floor [] Other

Storaç	ge wood or coal: [ ] Basement [ ] Outdoors [ ] Main Floor [X] Other N/A
Firepla	ace(s) located in: [ ] Basement [ ] Main Floor [X] Other N/A
Air co	nditioning: [ ] Central Air [ ] Window units [ ] Open Windows [X] None
Dehun	nidification: [ ] Stand alone unit [ ] Located on central air system [X] NA
Are th	ere air distribution ducts present? [X] Y [ ] N
6. OCCUPANO	CY is basement/lowest level occupied?
[] Full-time	e [ ] Occasionally [X] Seldom [ ] Almost Never
Level	General Use of Each Floor (e.g., family room, bedroom, laundry, storage, etc.)
Basement	Laundry, Utilities, Storage
1 Floor	Residential
2 Floor	None
a. Is there b. Does th c. Are pet d. Has the e. Is a ker f. Is there g. Is there h. Is there i. Is there j. Is there k. Baseme l. Are there	an attached garage? [ ] Y [X] N  be garage have a separate heating unit? [ ] Y [ ] N [X] NA  roleum-powered machines or vehicles stored in the garage? [ ] Y [X] N  building ever had a fire? [ ] Y [X] N When?  osene or unvented gas space heater present? [ ] Y [X] N Where?  a workshop or hobby/craft area? [X] Y [ ] N Where & type? See figure, Alaskan Crafts  smoking in the building? [X] Y [ ] N How frequently? Unknown  a kitchen exhaust fan? [ ] Y [ ] N If yes, where vented? Unknown  a bathroom exhaust fan? [ ] Y [ ] N If yes, where vented? Unknown  a clothes dryer? [X] Y [ ] N Type: [X] Gas [ ] Electric Where vented:  ent windows? [ ] Y [X] N Type: [X] Casement [ ] Awning [ ] Glass block Condition:  re exterior doors in the basement (e.g. "Bilco")? [ ] Y [ X] N [ ] NA
	se describe:(b) (6)in duplex units
	the building occupants use solvents at work (e.g., chemical manufacturing or laboratory, auto auto body shop, painting, fuel oil delivery, cosmetologist)? [ ] Y [ ] N UNKNOWN
If yes,	what types of solvents are used?
If yes,	are their clothes washed at work? [ ] Y [ ] N
Do any of the	ne building occupants regularly use or work at a dry-cleaning service?
	se dry-cleaning regularly (i.e., weekly): [ ] Y [X] N
	se dry-cleaning infrequently (i.e., monthly or less): [ ] Y [ ] N [X] Unknown
Yes, w	ork at a dry-cleaning service: [ ] Y [X] N

8. WATER AND SEWAGE
Water Supply: [X] Public Water [ ] Drilled Well [ ] Driven Well [ ] Dug Well [ ] Other:
Sewage Disposal: [X] Public Sewer [ ] Septic Tank [ ] Leach Field [ ] Dry Well [ ] Other:
9. OTHER ENVIRONMENTAL HAZARDS OBSERVED  Note factors that may impact vapor mitigation system installation or other construction activities:
A. Potential Asbestos: [ ] Yes [ ] No [X] Suspected
1. Location & Estimated Quantity:
2. General Condition: [ ] Good [ X] Fair [ ] Poor
3. Other Comments: Pre 1981 construction.
B: Potential Lead Paint: [ ] Yes [ ] No [X] Suspected
Location & Estimated Quantity: Walls & Floors
2. General Condition: [ ] Good [ ] Fair [ ] Poor
3. Other Comments: Pre 1981 construction.
10. BASEMENT FLOOR PLANS See attached figure.
11. TEMPORARY STORAGE
Is temporary storage required during performance of the removal action? [X] Y [ ] N
If yes, describe:Utilities, washer & dryer, personal property and work shop. See photos.
12. DAMAGE TO FIXTURE/FURNISHINGS
Must any fixtures or furnishings such as carpet or tile, be damaged or removed to perform the removal action?
[X] Y [ ] N
If yes, describe: _Old liner to be replaced with new.
13. NOTE ANY OTHER CONSIDERATIONS THAT MAY EFFECT THE REMOVAL ACTION
Are there any other performance-related concerns or issues (e.g., objects to be moved in crawl spaces, large
furnishings to be moved, etc.)? [X] Y [ ] N

If yes, describe: \_Crawl space, electrical wiring, and personal property storage.



TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 1 736 East 3rd Avenue North & South Duplexes.

Direction: Northeast Date: 2/24/14 Time: 12:50



Photo 2 Ductwork in crawl space.

Direction: North Date: 2/22/14 Time: 12:17

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 3 Ductwork in crawl space.

Direction: Northeast Date: 2/22/14 Time: 12:17



Photo 4 Ductwork in crawl space.

Direction: East Date: 2/22/14 Time: 12:17

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 5 Crawl space.

Direction: East Date: 2/22/14 Time: 12:17



Photo 6 Crawl space liner.

Direction: East/Down Date: 2/22/14 Time: 12:17

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 7 Exposed gravel beneath crawl space liner.

Direction: Northeast Date: 2/22/14 Time: 12:18

(b) (6)

Photo 8 North room looking into work shop shelves.

Direction: South Date: 2/22/14 Time: 12:19

TDD Number: 13-08-0020 Photographed by: Carl Overpeck




Photo 9 Sewer pipe penetrating slab with exposed gravel.

Direction: Down Date: 2/22/14 Time: 12:19



Photo 10 Pipe runs between north room and work shop.

Direction: Down Date: 2/22/14 Time: 12:19

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 11 Lined west wall.

Direction: Northwest Date: 2/22/14 Time: 12:21
(b) (6)

Photo 12 Lined west wall in work shop.

Direction: Southwest Date: 2/22/14 Time: 12:21

TDD Number: 13-08-0020 Photographed by: Carl Overpeck




Photo 13 Structural post in crawl space near stairwell.

Direction: Southeast Date: 2/22/14 Time: 12:23



Photo 14 Forced air furnace.

Direction: Northeast Date: 2/22/14 Time: 12:24

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 15 Liner on wall.

Direction: Northwest Date: 2/22/14 Time: 12:27



Photo 16 Crawl space.

Direction: Northeast Date: 2/22/14 Time: 12:27

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 17 Detergents etc. in laundry room.

Direction: Northwest Date: 2/22/14 Time: 12:28

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 18 Floor patch between north room and work shop.

Direction: Down Date: 2/22/14 Time: 12:28

TDD Number: 13-08-0020 Photographed by: Carl Overpeck



Photo 19 Work shop.

Direction: Northeast Date: 2/22/14 Time: 12:28



Photo 20 736 East 3rd Avenue North Duplex.

Direction: Northeast Date: 2/22/14 Time: 12:31